



**170 GPH  
MECHANICAL  
FUEL PUMP**

**IMPORTANT:** A thread locker (Loctite #243) has been applied to the inlet and outlet AN fittings. If the fittings have been removed, it is recommended that an equivalent thread locker be re-applied due to the varying expansion rates of aluminum and steel. This helps ensure that the fittings do not loosen in the housing during heat cycles.

199R-10201



**170 GPH  
MECHANICAL  
FUEL PUMP**

**IMPORTANT:** A thread locker (Loctite #243) has been applied to the inlet and outlet AN fittings. If the fittings have been removed, it is recommended that an equivalent thread locker be re-applied due to the varying expansion rates of aluminum and steel. This helps ensure that the fittings do not loosen in the housing during heat cycles.

199R-10201



**170 GPH  
MECHANICAL  
FUEL PUMP**

**IMPORTANT:** A thread locker (Loctite #243) has been applied to the inlet and outlet AN fittings. If the fittings have been removed, it is recommended that an equivalent thread locker be re-applied due to the varying expansion rates of aluminum and steel. This helps ensure that the fittings do not loosen in the housing during heat cycles.

199R-10201



**170 GPH  
MECHANICAL  
FUEL PUMP**

**IMPORTANT:** A thread locker (Loctite #243) has been applied to the inlet and outlet AN fittings. If the fittings have been removed, it is recommended that an equivalent thread locker be re-applied due to the varying expansion rates of aluminum and steel. This helps ensure that the fittings do not loosen in the housing during heat cycles.

199R-10201



**170 GPH  
MECHANICAL  
FUEL PUMP**

**IMPORTANT:** A thread locker (Loctite #243) has been applied to the inlet and outlet AN fittings. If the fittings have been removed, it is recommended that an equivalent thread locker be re-applied due to the varying expansion rates of aluminum and steel. This helps ensure that the fittings do not loosen in the housing during heat cycles.

199R-10201



**170 GPH  
MECHANICAL  
FUEL PUMP**

**IMPORTANT:** A thread locker (Loctite #243) has been applied to the inlet and outlet AN fittings. If the fittings have been removed, it is recommended that an equivalent thread locker be re-applied due to the varying expansion rates of aluminum and steel. This helps ensure that the fittings do not loosen in the housing during heat cycles.

199R-10201